

## Inspection Report

Service Number:  
E20060523

### Product Description



Product Name	<b>Bracelet</b>
Quantity	3,000pcs
Supplier	ODMasia
Inspection date	Mar. 23, 2006
Inspection location	Hangzhou, Zhejiang
Inspector	Dominic Yang
Supervisor	Dominic Yang

### Inspection Standards

Inspection type	FRI
Sampling standard	MIL-STD-105E
Sampling level	SINGLE LEVEL II,
AQL for Critical defective	0
AQL for Major defective	2.5
AQL for Minor defective	4.0
Sample size for Cri/Maj/Min	125pcs
Total number of cartons	0
Number of inspected cartons	0

Measure checking on (2pcs)

Unit: mm  
Length: 225



Width: 20





Thickness: 2.22



Thickness: 2.26



Thickness: 2.04

Size checking of box

Unit: cm

Length: 24.0



Width: 4.0



High: 2.0



## List of defects

Defectives	Description	CRI	MAJ	MIN
Within AQL	Missed one elastic	0	0	2

Picture



	Bad edge	0	0	2
--	----------	---	---	---



	Black spot	0	0	2
--	------------	---	---	---



No round 0 0 1

Damaged 0 1 0

Surface roughness 0 1 0

Bad edge 0 1 0


One more elastic 0 0 2



Glued 0 1 0

Unglued 0 0 1

Number of defectives 0 5 10  
Maximum Allowed 0 7 10



## Remark

1. All goods have not been packed into export carton.

## Packing

### Unit packing

Each one was packed into one box.









## Inner packing

12pcs with 2 bags of silica gel / ploybag



## Production Pictures







## Other Pictures



## Cartons



Total-1



Total-2